



HD66100F

HD62002-A17

MN4464

P2	P3	BST	GOTO	HLT	0	EXP
P1	P4	FST	GSB	LBL	•	= EXE
P0	P1	log	ENG	+/-	1	3
reset	MODE	In	o'''	a b/c	2	+ -
2nd F	ALPHA	cos	hyp	(4	6
SHIFT		tan	sin)	5	× ÷
	M-	Min	XD	7	9	
	M+	MR	X←M	8	C	

MA151K

AC